Release Notes

Yealink Desktop Phones T53 / T53W / T54W / T57W

Product Version: Firmware v.96.87.133.3

Status: “General Availability”

Enreach GmbH
Robert-Bosch-Straße 1
44803 Bochum, Germany

No of pages: 6
Version: 1.0
Last Changes: 09.11.2026

Contents

1. Content of Product Release 3
1.1. Yealink Desktop Phone T5 Series 3
2. Document History 3
3. Product Version History 3
3.1. Understanding the Yealink Firmware Version format 3
4. Changes 3
4.1. New with Firmware v.96.87.133.3 3
4.2. New with Firmware v.96.87.133.2 4
4.3. New with Firmware v.96.86.133.4 4
4.4. New with Firmware v.96.86.133.3 4
4.5. New with Firmware v.96.86.133.2 5
4.6. New with Firmware v.96.86.133.1 5
4.7. New with Firmware v.96.85.133.8 5
4.8. New with Firmware v.96.85.133.6 5
4.9. New with Firmware v.96.85.133.4 5
5. Update Procedure 6
6. Supported Devices 6
7. Supported Swyx Versions 6
8. Support 6

1. Content of Product Release

1.1. Yealink Desktop Phone T5 Series

Component	Filename	Version/Build
Yealink T53	T54W(T57W,T53W,T53)-96.87.133.3.rom	v.96.87.133.3
Yealink T53W	T54W(T57W,T53W,T53)-96.87.133.3.rom	v.96.87.133.3
Yealink T54W	T54W(T57W,T53W,T53)-96.87.133.3.rom	v.96.87.133.3
Yealink T57W	T54W(T57W,T53W,T53)-96.87.133.3.rom	v.96.87.133.3

2. Document History

Version	Date	Remarks	Editor
1.0	09.11.2026	Initial creation for product firmware release version v.96.87.133.3	Product Management
1.1	11.11.2026	Review	Product Management

3. Product Version History

Version	Date	Remarks
v.96.87.133.3	11.11.2026	Usable with Swyx 14.20 and higher
v.96.87.133.2	30.09.2025	Usable with Swyx 14
v.96.86.133.4	15.01.2024	Usable with Swyx 13.2x
v.96.86.133.3	14.08.2023	Usable with Swyx 13.2x
v.96.86.133.2	24.06.2022	Usable with Swyx 13.x
v.96.86.133.1	07.02.2022	Useable with Swyx 13/13.10
v.96.85.133.8	04.08.2021	Useable with Swyx 12.4x/13
v.96.85.133.6	08.06.2021	Useable with Swyx 12.4x
v.96.85.133.4	25.05.2021	Useable with Swyx 12.4x

3.1. Understanding the Yealink Firmware Version format

The Yealink firmware version format consist of 4 number blocks, here v.96.87.133.3

- First block: Product ID, here 96 stands for the T5-series
- Second block: Major FW version, here 87
- Third block: OEM-ID, here 133, stands for the Swyx/Enreach version
- Forth block: Minor FW version, here 3

4. Changes

4.1. New with Firmware v.96.87.133.3

This version is a maintenance release that includes several security and maintenance updates, which further increase the overall security, stability and performance of the devices. In addition, the

following issues in the context of a usage with Swyx are especially addressed within this firmware release:

- Fixed the issue that the German keyboard layout (Umlauts - ä, ö, ü, ß) was no longer available on the Yealink T57W after updating to firmware v.96.87.133.2.
- Fixed the issue that under certain circumstances (VLAN-ID gets distributed via DHCP) a phone received a new IP address every 60 seconds.

It is highly recommended to update all Yealink T5 series phones to this version.

Note: As with v.96.87.133.2, a downgrade to earlier major versions (prior to .87) or to other OEM versions is not possible.

4.2. New with Firmware v.96.87.133.2

This version does not include any Swyx-specific bug fixes or features, but it does include a number of general product improvements, particularly in the area of cybersecurity.

- Security policy update for all models
- Scheduled restart
- Energy-Saving mode
- Barrier-free improvements
- Bluetooth headset supports fast paring

Most features can be configured individually via the device's Web UI or uploaded as flexible provisioning parameters via Swyx Control Center on a device-specific basis.

Note: Please note that after updating to major version .87, it is no longer possible to downgrade to earlier major versions. This also applies to any downgrades to other OEM versions.

4.3. New with Firmware v.96.86.133.4

Beside a couple of generic fixes and improvements the following issues in the context of a usage with Swyx are especially addressed within this firmware release:

- Fixed the issue that dialing a number from a speed dial always picks the first line, if another line is chosen
- Fixed the issue that the call was hung up if no one answered the blind transfer for 30 seconds.

Hint: The fix for the blind call transfer issue is a combined fix and is working properly only with Swyx 13.30 and higher.

4.4. New with Firmware v.96.86.133.3

Beside a couple of generic fixes and improvements the following issues in the context of a usage with Swyx are especially addressed within this firmware release:

- DND (Do Not Disturb) status icon is not displayed on an Expansion Module connected to a T53(W).

Known issue: Changed behavior in the case of blind call transfer initiated by a Yealink phone. From firmware version 96.86.133.2 the call is cancelled if the called destination does not accept the call within a certain time slot (~30sec). In former versions the call was returned to the transferring Yealink phone

4.5. New with Firmware v.96.86.133.2

Beside a couple of generic fixes and improvements the following issues in the context of a usage with Swyx are especially addressed within this firmware release:

- Configurable parameter for the SIP-cause in the case of deactivated Call Waiting function (prevent secondary call). The parameter is set automatically with Swyx 13.20 and is now consistent with the SIP-cause of the other Swyx clients.
- Configurable parameter for call pickup in CTI case. Will be set automatically with Swyx 13.20. Requires a mandatory SwyxIt! 13.20. This firmware is the prerequisite for this newly introduced feature in Swyx 13.20.

4.6. New with Firmware v.96.86.133.1

Beside a couple of generic fixes and improvements the following issues in the context of a usage with Swyx are especially addressed within this firmware release:

- Fixed an issue in CTI mode with an outgoing call when another call is already connected.
- Fixed some issues in the context of Smart Noise Filtering.
- Supports the latest hardware revision of Yealink T5 phones.
- Optimized quick positioning bar in Directory/Call History in T57W

4.7. New with Firmware v.96.85.133.8

Beside a couple of generic fixes and improvements the following issues in the context of a usage with Swyx are especially addressed within this firmware release:

- Fixed an issue with the renewing of an IP-address via DHCP.
- Fixed the issue with the update of the presence status on the speed dials after the loss of the server connection.
- An issue in uaCSTA mode (CTI support) - SwyxIt! displays call as connected although call is still ringing.
- Fixed the issue that after plug-in a USB headset (or the EHS-USB adapter) to a phone the display was frozen.

Known issue: In specific scenarios/hardware combination the LEDs on an expansion module will not light (T57W). The presence status of the user is nevertheless shown on the display of the expansion module.

4.8. New with Firmware v.96.85.133.6

Beside a couple of generic fixes and improvements the following issues in the context of a usage with Swyx are especially addressed within this firmware release:

- Fixed an issue with the newly introduced extended status signaling (Away, Busy, Logoff) (Prerequisite SwyxWare 12.40).

Known issue: If the phone loses its connection to the server (e.g., due to a reboot of the services), it could be that subsequently the presence status on the speed dials will no longer be updated. Log-Off and following Log-On of the user heals that issue.

4.9. New with Firmware v.96.85.133.4

Initial release of Yealink T5 series for the usage with SwyxWare 12.40

- Extended status signaling (Away, Busy, Logoff) (Prerequisite SwyxWare 12.40)

- Call number suppression from SwyxIt! (Prerequisite SwyxWare 12.40)
- DE keyboard layout (Umlauts - ä, ö, ü, ß)
- VisualGroups support (Prerequisite SwyxWare 12.40)
- Fixed compatibility issues between SWYX T4XS and DECT headsets.

5. Update Procedure

The firmware will become available via the Enreach FIS server for Swyx. Downloading the firmware and distributing it to all connected Yealink phones can be simply done within the Swyx Control Center SCC.

All necessary steps are described in the Swyx Online Help, see “DISTRIBUTING SOFTWARE TO CLIENTS OR DEVICES”

Do only use officially by Swyx released firmware for Swyx platforms. Other firmware is not supported.

In the case of an internal software deployment (e.g. because phones have no access to the Internet) the firmware can be downloaded from the Enreach Help Center.

6. Supported Devices

Product	Status	Preferred Version
Yealink T53	Current	v.96.87.133.3
Yealink T53W	Current	v.96.87.133.3
Yealink T54W	Current	v.96.87.133.3
Yealink T57W	Current	v.96.87.133.3

We recommend customers use the “Preferred Version” for the given products. The preferred software versions offer tested and confirmed level of functionality. However, the devices might also operate with older or newer software version with the caveat that recently added interoperability, or advanced features may not be possible when using these versions. In cases, if a defect is found when using other versions, it may be necessary to update to the supported version.

7. Supported Swyx Versions

Product	Preferred Version	Supported Version
Swyx	Swyx 15	Swyx 14.20 and higher
SwyxON		

We recommend customers use the “Preferred Version” for the given products. The supported software versions offer tested and confirmed level of functionality. However, the devices might also operate with older or newer software version with the caveat that recently added interoperability or advanced features may not be possible when using these versions. In cases, if a defect is found when using other versions, it may be necessary to update to the supported version.

8. Support

The Support for the customized Yealink Firmware for Swyx is handled through the regular Enreach support process for Swyx.